

## ActSafe Safety Alerts

### February 2021

Additional information on how to descend with PMX and ACX. 16/02/2021

Link: [https://cdn-dotcom-prod.skylotec.com/media/5f/1c/de/1751456213/ActSafe\\_Additional information PMX and ACX.pdf?ts=1751456213](https://cdn-dotcom-prod.skylotec.com/media/5f/1c/de/1751456213/ActSafe_Additional information PMX and ACX.pdf?ts=1751456213)

Incident reports: Dropped ACX and Batteries. 16/02/2021

Link: [https://cdn-dotcom-prod.skylotec.com/media/73/88/a1/1751456213/ActSafe\\_Incident reports\\_Dropped ACX and Batteries.pdf?ts=1751456213](https://cdn-dotcom-prod.skylotec.com/media/73/88/a1/1751456213/ActSafe_Incident reports_Dropped ACX and Batteries.pdf?ts=1751456213)

### August 2019

Incident with ACCII: Rope sheath damage 12/08/2019

Link: [https://cdn-dotcom-prod.skylotec.com/media/06/a6/e3/1751456214/ActSafe\\_GENERAL SAFETY NOTICE.pdf?ts=1751456214](https://cdn-dotcom-prod.skylotec.com/media/06/a6/e3/1751456214/ActSafe_GENERAL SAFETY NOTICE.pdf?ts=1751456214)

### September 2015

Velcro retrofit on rope cover. Important information to all distributors and end-users of ActSafe ACCII Power Ascenders 01/09/2015

Link: [https://cdn-dotcom-prod.skylotec.com/media/61/fd/e6/1751456213/ActSafe\\_ACCII\\_important safety updates.pdf?ts=1751456213](https://cdn-dotcom-prod.skylotec.com/media/61/fd/e6/1751456213/ActSafe_ACCII_important safety updates.pdf?ts=1751456213)

### November 2014

Rope care 27/11/2014

Link: [https://cdn-dotcom-prod.skylotec.com/media/1a/e0/ae/1751456213/ActSafe\\_safetynotice\\_rope\\_soaking.pdf?ts=1751456213](https://cdn-dotcom-prod.skylotec.com/media/1a/e0/ae/1751456213/ActSafe_safetynotice_rope_soaking.pdf?ts=1751456213)

GENERAL SAFETY NOTICE 27/11/2014

Link: [https://cdn-dotcom-prod.skylotec.com/media/06/a6/e3/1751456214/ActSafe\\_GENERAL SAFETY NOTICE.pdf?ts=1751456214](https://cdn-dotcom-prod.skylotec.com/media/06/a6/e3/1751456214/ActSafe_GENERAL SAFETY NOTICE.pdf?ts=1751456214)

## March 2013

Incident during ACC II battery charging at Petzl V. Access 31/03/2013

Link: <https://cdn-dotcom->

[prod.skylotec.com/media/d3/ea/4f/1751456214/ActSafe\\_battery\\_safety\\_guidelines.pdf?ts=1751456214](https://cdn-dotcom-prod.skylotec.com/media/d3/ea/4f/1751456214/ActSafe_battery_safety_guidelines.pdf?ts=1751456214)

## March 2009

Important Safety Updates for ActSafe PME Power Ascenders 25/03/2009

Link: <https://cdn-dotcom->

[prod.skylotec.com/media/3d/ef/e6/1751456213/ActSafe\\_PME\\_important\\_safety](https://cdn-dotcom-prod.skylotec.com/media/3d/ef/e6/1751456213/ActSafe_PME_important_safety_updates.pdf?ts=1751456213)

[updates.pdf?ts=1751456213](https://cdn-dotcom-prod.skylotec.com/media/3d/ef/e6/1751456213/ActSafe_PME_important_safety_updates.pdf?ts=1751456213)

[https://cdn-dotcom-](https://cdn-dotcom-prod.skylotec.com/media/3d/ef/e6/1751456213/ActSafe_PME_important_safety_updates.pdf?ts=1751456213)

[prod.skylotec.com/media/3d/ef/e6/1751456213/ActSafe\\_PME\\_important\\_safety](https://cdn-dotcom-prod.skylotec.com/media/3d/ef/e6/1751456213/ActSafe_PME_important_safety_updates.pdf?ts=1751456213)

Important Safety Updates for ActSafe ACC Power Ascender 25/03/2009

Link: <https://cdn-dotcom->

[prod.skylotec.com/media/99/94/bd/1751456213/ActSafe\\_ACC\\_important\\_safety](https://cdn-dotcom-prod.skylotec.com/media/99/94/bd/1751456213/ActSafe_ACC_important_safety_updates.pdf?ts=1751456213)

[updates.pdf?ts=1751456213](https://cdn-dotcom-prod.skylotec.com/media/99/94/bd/1751456213/ActSafe_ACC_important_safety_updates.pdf?ts=1751456213)

[https://cdn-dotcom-](https://cdn-dotcom-prod.skylotec.com/media/99/94/bd/1751456213/ActSafe_ACC_important_safety_updates.pdf?ts=1751456213)

[prod.skylotec.com/media/99/94/bd/1751456213/ActSafe\\_ACC\\_important\\_safety](https://cdn-dotcom-prod.skylotec.com/media/99/94/bd/1751456213/ActSafe_ACC_important_safety_updates.pdf?ts=1751456213)